

Overhaul Plan - Head					
Engine Type		P/N	JPY	NEW JPY	NOTE
NISSAN A		31301010	Negotiable	Negotiable	We estimate separately
NISSAN L		31301020	Negotiable	Negotiable	We estimate separately
CA18DE(T)	Lash ADJ	31301050	¥247,000	¥249,000	
	Shim ADJ	31301060	¥280,000	¥282,000	
SR20DE(T)	Lash ADJ	31301070	¥203,000	¥206,000	
	Shim ADJ	31301080	¥236,000	¥239,000	
RB20,25DE(T)	Lash ADJ	31301090	¥282,000	¥287,000	
	Shim ADJ	31301100	¥326,000	¥331,000	
RB26DETT		31301110	¥326,000	¥331,000	
VG30DE(T)	Lash ADJ	31301140	¥361,000	¥376,000	
	Shim ADJ	31301150	¥405,000	¥420,000	
VQ35DE (HR)		31301130	¥405,000	¥420,000	
4G63		31301160	¥247,000	¥249,000	
4B11		31301120	¥307,000	¥317,000	
EJ20	Lash ADJ	31301240	¥239,000	¥245,000	
	Shim ADJ	31301250	¥261,000	¥267,000	
EJ25	Lash ADJ	31301300	¥239,000	¥245,000	
	Shim ADJ	31301310	¥261,000	¥267,000	
4AG	16VALVE	31301320	¥280,000	¥282,000	
	20VALVE	31301330	¥350,000	¥354,000	
1JZ (vvt-i)		31301340	¥379,000	¥394,000	
2JZ (vvt-i)		31301350	¥379,000	¥394,000	
3 cylinder DOHC	Lash ADJ	31301260	¥196,600	¥198,600	
	Shim ADJ	31301270	¥229,600	¥231,600	
4 cylinder DOHC	Lash ADJ	31301170	¥247,000	¥249,000	
	Shim ADJ	31301180	¥280,000	¥282,000	
4 cylinder boxer DOHC	Lash ADJ	31301280	¥283,000	¥296,000	
	Shim ADJ	31301290	¥305,000	¥318,000	
Inline 6 DOHC	Lash ADJ	31301190	¥335,000	¥350,000	
	Shim ADJ	31301200	¥379,000	¥394,000	
V6 DOHC	Lash ADJ	31301210	¥361,000	¥376,000	
	Shim ADJ	31301220	¥405,000	¥420,000	

Overhaul Plan - Bottom end				
Engine Type	P/N	JPY	NEW JPY	NOTE
NISSAN A	32301010	Negotiable	Negotiable	We estimate separately
NISSAN L	32301020	Negotiable	Negotiable	We estimate separately
CA18DE(T)	32301050	¥310,800	¥311,500	
SR20DE(T)	32301070	¥310,800	¥311,500	
RB20,25DE(T)	32301090	¥427,800	¥439,500	<ul style="list-style-type: none"> Needs ¥ 10,000 extra for RB22,24 ¥ 32,000 extra is needed for assembling FR diif
RB26DETT	32301110	¥427,800	¥439,500	<ul style="list-style-type: none"> ¥ 32,000 extra is needed for assembling FR diif
VG30DE(T)	32301140	¥473,000	¥479,500	
VQ35DE (HR)	32301130	¥473,000	¥479,500	
4G63	32301160	¥310,800	¥311,500	
4B11	32301150	¥310,800	¥311,500	
EJ20	32301210	¥317,800	¥340,500	
EJ25	32301240	¥317,800	¥340,500	
4AG	32301250	¥310,800	¥311,500	
1JZ (vvt-i)	32301260	¥427,800	¥439,500	
2JZ (vvt-i)	32301270	¥427,800	¥439,500	
3 cylinder	32301220	¥278,000	¥280,500	
4 cylinder	32301170	¥310,800	¥318,500	
4 cylinder boxer	32301230	¥357,800	¥366,500	
Inline 6	32301180	¥427,800	¥439,500	
V6	32301190	¥473,000	¥479,500	

Engine overhaul Plan					
Engine Type		P/N	JPY	NEW JPY	NOTE
NISSAN A		33301010	Negotiable	Negotiable	We estimate separately
NISSAN L		33301020	Negotiable	Negotiable	We estimate separately
CA18DE(T)	Lash ADJ	33301050	¥523,300	¥530,000	
	Shim ADJ	33301060	¥567,300	¥574,000	
SR20DE(T)	Lash ADJ	33301070	¥523,300	¥530,000	
	Shim ADJ	33301080	¥567,300	¥574,000	
RB20,25DE(T)	Lash ADJ	33301090	¥701,600	¥714,300	・ Needs ¥ 10,000 extra for RB22,24 ・ ¥ 32,000 extra is needed for assembling FR diif
	Shim ADJ	33301100	¥767,600	¥780,300	
RB26DETT		33301110	¥761,600	¥774,300	・ ¥ 32,000 extra is needed for assembling FR diif
VG30DE(T)	Lash ADJ	33301140	¥844,000	¥861,500	
	Shim ADJ	33301150	¥910,000	¥927,500	
VQ35DE (HR)		33301130	¥910,000	¥927,500	
4G63		33301160	¥523,300	¥530,000	
4B11		33301230	¥567,300	¥574,000	
EJ20	Lash ADJ	33101240	¥615,800	¥622,500	
	Shim ADJ	33101250	¥659,800	¥666,500	
EJ25	Lash ADJ	33301240	¥615,800	¥622,500	
	Shim ADJ	33301250	¥659,800	¥666,500	
4AG	16VALVE	33301260	¥611,300	¥617,000	
	20VALVE	33301270	¥664,300	¥678,000	
1JZ (vvt-i)		33301280	¥814,600	¥837,300	
2JZ (vvt-i)		33301290	¥814,600	¥837,300	
3 cylinder DOHC	Lash ADJ	33101260	¥494,100	¥498,600	
	Shim ADJ	33101270	¥527,100	¥531,600	
4 cylinder DOHC	Lash ADJ	33301170	¥567,300	¥573,000	
	Shim ADJ	33301180	¥611,300	¥617,000	
4 cylinder boxer DOHC	Lash ADJ	33101280	¥659,800	¥665,500	
	Shim ADJ	33101290	¥703,800	¥709,500	
Inline 6 DOHC	Lash ADJ	33301190	¥748,600	¥771,300	
	Shim ADJ	33301200	¥814,600	¥837,300	
V6 DOHC	Lash ADJ	33301210	¥844,000	¥861,500	
	Shim ADJ	33301220	¥910,000	¥927,500	

MODIFICATION PLAN - BOTTOM END				
Engine Type	P/N	JPY	NEW JPY	NOTE
3 cylinder	32302040	¥149,000	¥151,500	
4 cylinder	32302010	¥138,800	¥146,500	
4 cylinder boxer	32302050	¥163,000	¥172,500	
Inline 6	32302020	¥169,800	¥181,500	
V6	32302030	¥215,000	¥221,500	

MODIFICATION PLAN - HEAD					
Engine Type	P/N	JPY	NEW JPY	NOTE	
NISSAN A	31302000	¥87,000	¥87,000	no changes	
NISSAN L	31302010	¥127,000	¥129,000		
CA18DE(T)	31302020	¥115,000	¥118,000		
SR20DE(T)	31302030	¥115,000	¥118,000		
RB20,25DE(T)	31302040	¥172,000	¥177,000		
RB26DETT	31302080	¥172,000	¥177,000		
VG30DE(T)	31302170	¥229,000	¥244,000		
VQ35DE (HR)	31302180	¥229,000	¥244,000		
VR38DETT	31302250	¥176,000	¥181,000		
4G63	31302120	¥115,000	¥118,000		
4B11	31302190	¥115,000	¥118,000		
EJ20	31302140	¥121,000	¥124,000		
EJ25	31302200	¥121,000	¥124,000		
4AG	16VALVE	31302210	¥159,000	¥161,000	
	20VALVE	31302220	¥190,000	¥200,000	
1JZ (vvt-i)	31302230	¥225,000	¥240,000		
2JZ (vvt-i)	31302240	¥225,000	¥240,000		
3 cylinder DOHC	31302150	¥119,600	¥121,600		
4 cylinder DOHC	31302050	¥159,000	¥161,000		
4 cylinder boxer DOHC	31302160	¥165,000	¥167,000		
Inline 6 DOHC	31302060	¥225,000	¥240,000		
V6 DOHC	31302070	¥229,000	¥244,000		
4 cylinder OHC	31302090	¥87,000	¥87,000	no changes	
Inline 6 OHC	31302100	¥127,000	¥129,000		
V6 OHC	31302110	¥131,000	¥133,000		

MODIFICATION PLAN							
Service	Engine Type	P/N	JPY	NEW JPY	NOTE		
Modification for bigger Cam	RB26	31101010	¥32,000	¥32,000			
Shim adjustment	CA18DE(T)	31102070	¥38,000	¥38,000			
	SR20DE(T)	31102080	¥38,000	¥38,000			
	RB20,25DE(T)	31102090	¥56,000	¥56,000			
	RB26DETT	31102100	¥56,000	¥56,000			
	VG30DE(T)	31102110	¥59,000	¥59,000			
	VQ35DE (HR)	31102120	¥59,000	¥59,000			
	4G63	31102130	¥38,000	¥38,000			
	4B11	31102140	¥38,000	¥38,000			
	EJ20	31102150	¥42,000	¥42,000			
	EJ25	31102160	¥42,000	¥42,000			
	4AG	16VALVE	31102170	¥38,000	¥38,000		
		20VALVE	31102180	¥48,000	¥48,000		
	1JZ (vvt-i)	31102190	¥56,000	¥56,000			
	2JZ (vvt-i)	31102200	¥56,000	¥56,000			
	Inline DOHC	12VALVE	31102040	¥30,000	¥30,000	no changes	
		16VALVE	31102010	¥38,000	¥38,000		
		20VALVE	31102050	¥48,000	¥48,000		
		24VALVE	31102020	¥56,000	¥56,000		
4 cylinder boxer	16VALVE	31102060	¥42,000	¥42,000			
V 6	24VALVE	31102030	¥59,000	¥59,000			
Head polishing	grind thickness ~2.0mm	3 cylinder	31103070	¥9,000	¥9,000		
		4 cylinder	31103010	¥10,000	¥10,000		
		4 cylinder boxer	31103080	¥16,000	¥16,000		
		Inline 6	31103020	¥14,000	¥14,000		
		V 6	31103030	¥18,000	¥18,000		
	grind thickness 2.1mm~	3 cylinder	31103090	¥13,000	¥13,000		
		4 cylinder	31103040	¥14,000	¥14,000		
		4 cylinder boxer	31103110	¥22,000	¥22,000		
		Inline 6	31103050	¥18,000	¥18,000		
		V 6	31103060	¥26,000	¥26,000		

ヘッド加工						
Service	Engine Type	P/N	JPY	NEW JPY	NOTE	
Port polishing	CA18DE(T)	31104060	¥176,000	¥186,000		
	SR20DE(T)	31104070	¥176,000	¥186,000		
	RB20,25DE(T)	31104080	¥264,000	¥274,000		
	RB26DETT	31104090	¥264,000	¥274,000		
	VG30DE(T)	31104100	¥264,000	¥274,000		
	VQ35DE (HR)	31104110	¥264,000	¥274,000		
	4G63	31104120	¥176,000	¥186,000		
	4B11	31104130	¥176,000	¥186,000		
	EJ20	31104140	¥176,000	¥186,000		
	EJ25	31104150	¥176,000	¥186,000		
	4AG	16VALVE	31104160	¥176,000	¥186,000	
		20VALVE	31104170	¥220,000	¥230,000	
	1JZ (vvt-i)	31104180	¥264,000	¥274,000		
	2JZ (vvt-i)	31104190	¥264,000	¥274,000		
	8 VALVE	31104010	¥88,000	¥98,000		
	12 VALVE	31104020	¥132,000	¥142,000		
	16 VALVE	31104030	¥176,000	¥186,000		
	20 VALVE	31104050	¥220,000	¥230,000		
	24 VALVE	31104040	¥264,000	¥274,000		
	Port smoothning	3 cylinder	31105030	¥45,000	¥48,000	
4 cylinder		31105010	¥60,000	¥64,000		
6 cylinder		31105020	¥90,000	¥96,000		
Valvespring cleaning* assembly	1 VALVE	31106010	¥1,200	¥2,000		
	8 VALVE	31106020	¥8,000	¥8,000		
	12 VALVE	31106030	¥12,000	¥12,000		
	16 VALVE	31106040	¥16,000	¥16,000		
	20 VALVE	31106050	¥20,000	¥20,000		
	24 VALVE	31106060	¥24,000	¥24,000		
Cylinder head water jacket modification	Boring	RB26	31107010	¥18,000	¥18,000	no changes
	Boring + plug replacement		31107020	¥26,000	¥26,000	
	Plug replacement(F,R)		31108010	¥10,000	¥10,000	
Cylinder argon weld	Welding	1箇所	31109010	¥12,000	¥12,000	
	Welding + bend correction	L6	31109020	¥40,000	¥40,000	
Cylinder capacity adj	Capacity adj + head polishing	3 cylinder	31110060	¥30,000	¥30,000	
		4 cylinder	31110070	¥40,000	¥40,000	
		4 cylinder boxer	31110080	¥44,000	¥44,000	
		Inline 6	31110090	¥60,000	¥60,000	
		V 6	31110100	¥66,000	¥66,000	
	Cylinder modification Capacity adj + Head polishing	3 cylinder	31110030	¥39,000	¥39,000	
		4 cylinder	31110010	¥52,000	¥52,000	
		4 cylinder boxer	31110040	¥59,000	¥60,000	
		Inline 6	31110020	¥78,000	¥78,000	no changes
		V 6	31110050	¥88,000	¥90,000	
Valve lapping	1 VALVE	31111010	¥800	¥800		
Valve polishing	Each Valve	31112010	¥1,000	¥1,000	no changes	
Stud cam cap bearing bolt assembly	RB26,25,20	31113010	¥7,000	¥7,000		

VALVE GUIDE REPLACEMENT				
Engine Type	P/N	JPY	NEW JPY	NOTE
L6	31303020	¥101,000	¥103,000	
CA18DE(T)	31303170	¥89,000	¥92,000	
SR20DE(T)	31303040	¥89,000	¥92,000	
RB20,25DE(T)	31303050	¥134,000	¥139,000	
RB26DETT	31303060	¥134,000	¥139,000	
VR38DETT	31303180	¥134,000	¥139,000	
4G63	31303130	¥89,000	¥92,000	
4B11	31303150	¥89,000	¥92,000	
EJ20	31303140	¥89,000	¥92,000	
EJ25	31303160	¥89,000	¥92,000	
1 VALVE	31303070	¥9,200	¥9,200	no changes
8 VALVE	31303080	¥69,000	¥69,000	
12 VALVE	31303090	¥101,000	¥103,000	
16 VALVE	31303100	¥133,000	¥135,000	
20 VALVE	31303110	¥160,000	¥170,000	
24 VALVE	31303120	¥187,000	¥202,000	

VALVE GUIDE REPLACEMENT/DETAILS					
Service	Engine Type	P/N	JPY	NEW JPY	NOTE
Valve guide replacement Material: phosphor bronz (PBB)	L6	31114020	¥65,000	¥67,000	
	CA18DE(T)	31114170	¥41,000	¥44,000	
	SR20DE(T)	31114040	¥41,000	¥44,000	
	RB20,25DE(T)	31114050	¥62,000	¥67,000	
	RB26DETT	31114060	¥62,000	¥67,000	
	VR38DETT	31114180	¥62,000	¥67,000	
	4G63	31114130	¥41,000	¥44,000	
	4B11	31114150	¥41,000	¥44,000	
	EJ20	31114140	¥41,000	¥44,000	
	EJ25	31114160	¥41,000	¥44,000	
	1 VALVE	31114070	¥6,000	¥6,000	no changes
	8 VALVE	31114080	¥45,000	¥45,000	
	12 VALVE	31114090	¥65,000	¥67,000	
	16 VALVE	31114100	¥85,000	¥87,000	
	20 VALVE	31114110	¥100,000	¥110,000	
24 VALVE	31114120	¥115,000	¥130,000		
Valve guide replacement (Using provided valve guide)	1 VALVE	31115010	¥1,100	¥1,500	
	8 VALVE	31115020	¥8,800	¥10,000	
	12 VALVE	31115030	¥13,000	¥15,000	
	16 VALVE	31115040	¥17,000	¥20,000	
	20 VALVE	31115050	¥22,000	¥26,000	
Valve guide replacement + valve seat cut + valve length adj (Using provided valve guide)	24 VALVE	31115060	¥26,000	¥31,000	
	1 VALVE	31116010	¥4,300	¥4,700	
	8 VALVE	31116020	¥32,800	¥34,000	
	12 VALVE	31116030	¥49,000	¥51,000	
	16 VALVE	31116040	¥65,000	¥68,000	
20 VALVE	31116050	¥82,000	¥86,000		
24 VALVE	31116060	¥98,000	¥103,000		

VALVE SEAT RING REPLACEMENT					
Material	Engine Type	P/N	JPY	NEW JPY	NOTE
Heat resisting steel	1 VALVE	31304010	¥7,800	¥9,500	
	8 VALVE	31304020	¥60,000	¥75,000	
	12 VALVE	31304030	¥90,000	¥112,000	
	16 VALVE	31304040	¥120,000	¥147,000	
	20 VALVE	31304050	¥150,000	¥186,000	
	24 VALVE	31304060	¥178,000	¥222,000	
Beryllium	1 VALVE	31305010	¥13,000	¥15,600	
	8 VALVE	31305020	¥104,000	¥125,000	
	12 VALVE	31305030	¥156,000	¥187,000	
	16 VALVE	31305040	¥208,000	¥245,000	
	20 VALVE	31305050	¥260,000	¥310,000	
	24 VALVE	31305060	¥312,000	¥370,000	
	VR38DETT	31305180	¥235,000	¥264,000	
	RB26	31305080	¥235,000	¥264,000	
	SR20	31305070	¥156,000	¥176,000	
	EJ20	31305090	¥156,000	¥176,000	
	EJ25	31305170	¥156,000	¥176,000	
	4B11	31305140	¥156,000	¥176,000	
	4G63	31305130	¥156,000	¥176,000	

VALVE SEAT RING REPLACEMENT/DETAILS					
Service	Engine Type	P/N	JPY	NEW JPY	NOTE
Seat ring replacement (use provided seat ring)	1 VALVE	31117010	¥3,300	¥5,000	
	8 VALVE	31117020	¥24,000	¥34,000	
	12 VALVE	31117030	¥36,000	¥51,000	
	16 VALVE	31117040	¥48,000	¥68,000	
	20 VALVE	31117050	¥60,000	¥85,000	
	24 VALVE	31117060	¥72,000	¥102,000	
Seat ring replacement + Valve seat cutting + Valve set length adjustment (use provided seat ring)	1 VALVE	31118010	¥6,500	¥8,200	
	8 VALVE	31118020	¥48,000	¥58,000	
	12 VALVE	31118030	¥72,000	¥87,000	
	16 VALVE	31118040	¥96,000	¥116,000	
	20 VALVE	31118050	¥120,000	¥145,000	
Valve seat cutting + Valve set length adjustment	1 VALVE	31120010	¥3,200	¥3,200	
	8 VALVE	31120020	¥24,000	¥24,000	
	12 VALVE	31120030	¥36,000	¥36,000	
	16 VALVE	31120040	¥48,000	¥48,000	
	20 VALVE	31120050	¥60,000	¥60,000	
	24 VALVE	31120060	¥72,000	¥72,000	
Valve seat cutting (for large size valve) + Valve set length adjustment	1 VALVE	31120070	¥4,600	¥4,600	
	8 VALVE	31120080	¥34,000	¥34,000	
	12 VALVE	31120090	¥51,000	¥51,000	
	16 VALVE	31120100	¥68,000	¥68,000	
	20 VALVE	31120110	¥85,000	¥85,000	
Seat ring inner diameter expansion	1 VALVE	31121010	¥1,900	¥1,900	
	8 VALVE	31121020	¥14,000	¥14,000	
	12 VALVE	31121030	¥21,000	¥21,000	
	16 VALVE	31121040	¥28,000	¥28,000	
	20 VALVE	31121050	¥35,000	¥35,000	
	24 VALVE	31121060	¥42,000	¥42,000	

no changes

MODIFICATION PLAN - BOTTOM END						
Service	Engine Type	P/N	JPY	NEW JPY	NOTE	
Cylinder block polishing	amount ~1.0mm	3 cylinder	32101070	¥14,000	¥15,000	
		4 cylinder	32101010	¥16,000	¥17,000	
		4 cylinder boxer	32101080	¥24,000	¥25,000	
		Inline 6	32101020	¥20,000	¥21,000	
		V 6	32101030	¥30,000	¥31,000	
	amount 1.1mm~	3 cylinder	32101090	¥17,000	¥18,000	
		4 cylinder	32101040	¥20,000	¥21,000	
		4 cylinder boxer	32101100	¥30,000	¥31,000	
		Inline 6	32101050	¥25,000	¥26,000	
		V 6	32101060	¥38,000	¥39,000	
Cylinder block Plateau honing (amount ~ 0.09mm)	STD	3 cylinder	32102070	¥28,000	¥28,000	no changes
		4 cylinder	32102010	¥30,000	¥30,000	
		4 cylinder boxer	32102090	¥34,000	¥34,000	
		Inline 6	32102030	¥45,000	¥45,000	
		V 6	32102050	¥52,000	¥52,000	
	w/ dummy head	3 cylinder	32102080	¥36,000	¥36,000	
		4 cylinder	32102020	¥40,000	¥40,000	
		4 cylinder boxer	32102100	¥50,000	¥50,000	
		Inline 6	32102040	¥57,000	¥57,000	
		V 6	32102060	¥65,000	¥65,000	
Cylinder block boring + Plateau honing (amount 0.1~ 3.5mm)	STD	3 cylinder	32103090	¥34,000	¥34,000	
		4 cylinder	32103010	¥38,000	¥38,000	
		4 cylinder boxer	32103110	¥40,000	¥40,000	
		Inline 6	32103030	¥54,000	¥54,000	
		V 6	32103050	¥60,000	¥60,000	
	w/ dummy head	RB22,24	32103070	¥60,000	¥60,000	
		3 cylinder	32103100	¥40,000	¥40,000	
		4 cylinder	32103020	¥48,000	¥48,000	
		4 cylinder boxer	32103120	¥55,000	¥55,000	
		Inline 6	32103040	¥66,000	¥66,000	
V 6	32103060	¥75,000	¥75,000			
	RB22,24	32103080	¥72,000	¥72,000		
Dummy head + Plateau honing(w/ dummy head)	EJ20	32102110	¥58,000	¥58,000		
Dummy head + boring(w/ Dummy block) + Plateau honing	EJ20	32103130	¥70,000	¥70,000		
Head studs assembly		32105010	¥7,000	¥7,000		
Crank cap bearing studs assembly		32106010	¥7,000	¥7,000		
Cylinder block Modification for larger Con Rod (Bore up SR20 to 2.2L) (Bore up RB20 to 2.4L)		RB20/25/26	32104010	¥30,000	¥30,000	
	STD Con Rod	SR20	32104020	¥38,000	¥38,000	
	H-beam Con Rod		32104030	¥25,000	¥25,000	
		4G63	32104040	¥23,000	¥23,000	
		2JZ-GTE	3.6 ℓ	32104050	¥58,000	¥58,000
			3.4 ℓ	32104060	¥30,000	¥30,000
		EJ25	32104070	¥12,000	¥12,000	

PISTONS					
Service	Engine Type	P/N	JPY	NEW JPY	NOTE
Piston valve recessing	2 VALVE	32109010	¥5,500	¥5,500	※1気筒あたりの価格です。no changes
	4 VALVE	32109030	¥9,500	¥10,000	※1気筒あたりの価格です。
Piston head polishing	1 cylinder	32110010	¥5,000	¥5,000	no changes
Piston snap ring grooving + pin modification for full-flow	1 cylinder	32111010	¥6,000	¥6,000	
Piston weight adj	1 cylinder	32112010	¥4,000	¥4,000	
Piston oiljet modification	1 cylinder	32124010	¥6,000	¥6,000	

CONNECTING RODS					
Service	Engine Type	P/N	JPY	NEW JPY	NOTE
Con Rod bush modification	STD	32113010	¥8,000	¥8,000	no changes
	eccentric	32113020	¥10,000	¥10,000	
Con Rod weight adj	each rod	32115010	¥6,000	¥6,000	
Con Rod bearing metal assembly	4 cylinder	32116010	¥15,000	¥15,000	
	Inline 6, V6	32116020	¥22,000	¥22,000	
	NISSAN A	32116040	¥15,000	¥15,000	
	NISSAN L	32116050	¥22,000	¥22,000	
	CA18DE(T)	32116060	¥15,000	¥15,000	
	SR20DE(T)	32116070	¥15,000	¥15,000	
	RB20,25DE(T)	32116080	¥22,000	¥22,000	
	RB26DETT	32116090	¥22,000	¥22,000	
	VG30DE(T)	32116100	¥22,000	¥22,000	
	VQ35DE (HR)	32116110	¥22,000	¥22,000	
	4G63	32116120	¥15,000	¥15,000	
	4B11	32116130	¥15,000	¥15,000	
	EJ20	32116140	¥18,000	¥18,000	
	EJ25	32116150	¥18,000	¥18,000	
4AG	32116160	¥15,000	¥15,000		
1JZ	32116170	¥22,000	¥22,000		
2JZ	32116180	¥22,000	¥22,000		

CRANKSHAFT						
Service	Engine Type	P/N	JPY	NEW JPY	NOTE	
Crankshaft dynamic balancing	STD	4 cylinder	32117010	¥14,000	¥16,000	
		Inline 6	32117020	¥18,800	¥24,000	
		V6,3 cylinder	32117030	¥45,000	¥45,000	
	Lightweight	4 cylinder	32117040	¥28,000	¥28,000	no changes
		6 cylinder	32117050	¥30,000	¥30,000	
Crankshaft bent correction		32118010	¥11,000	¥12,500		
Crankshaft lapping	4 cylinder	32119010	¥23,000	¥23,000	no changes	
	6 cylinder	32119030	¥30,000	¥30,000		
Crankshaft tu triding	L4,6	32120010	¥20,000	¥20,000		
Crankshaft bearing metal assembl	3 cylinder	32121030	¥15,000	¥15,000	Price of the bearing metal is not included /no changes	
	Inline 4	32121010	¥18,000	¥22,000	Price of the bearing metal is not included	
	4 cylinder boxer	32121040	¥28,000	¥33,000		
	Inline 6, V6	32121020	¥23,000	¥27,000		
	NISSAN A	32121050	¥18,000	¥22,000		
	NISSAN L	32121060	¥23,000	¥27,000		
	CA18DE(T)	32121070	¥18,000	¥22,000		
	SR20DE(T)	32121080	¥18,000	¥22,000		
	RB20,25DE(T)	32121090	¥23,000	¥27,000		
	RB26DETT	32121100	¥23,000	¥27,000		
	VG30DE(T)	32121110	¥23,000	¥27,000		
	VQ35DE (HR)	32121120	¥23,000	¥27,000		
	4G63	32121130	¥18,000	¥22,000		
	4B11	32121140	¥18,000	¥22,000		
	EJ20	32121150	¥28,000	¥33,000		
	EJ25	32121160	¥28,000	¥33,000		
	4AG	32121170	¥18,000	¥22,000		
	1JZ (vvt-i)	32121180	¥23,000	¥27,000		
	2JZ (vvt-i)	32121190	¥23,000	¥27,000		
Crankshaft single key modi cation	L6	32122010	¥25,000	¥25,000	no changes	

FLYWHEEL					
Service		P/N	JPY	NEW JPY	NOTE
Flywheel balancing		34101010	¥9,000	¥15,000	
Clutch cover balancing		34101020	¥9,000	¥15,000	
Multiple plate clutch kit balancing		34101030	¥18,000	¥30,000	
Puley balancing		34101040	¥9,000	¥9,000	no changes

CAM MODIFICATION						
Service	Application	P/N	JPY	NEW JPY	NOTE	
Cam profile Modification	2cam	Japanese cars	34108010	¥16,000	¥18,000	
		Others	34108020	¥19,000	¥21,000	
	4cam	Japanese cars	34108030	¥18,000	¥20,000	
		Others	34108040	¥21,000	¥23,000	
	6cam	Japanese cars	34108050	¥24,000	¥26,000	
		Others	34108060	¥28,000	¥30,000	
	8cam	Japanese cars	34108070	¥28,000	¥30,000	
		Others	34108080	¥32,000	¥34,000	
	12cam	Japanese cars	34108090	¥34,000	¥36,000	
		Others	34108100	¥38,000	¥40,000	
	16cam	Japanese cars	34108110	¥44,000	¥46,000	
		Others	34108120	¥48,000	¥50,000	
	Manganese phosphate treatment	1 shaft	34108130	¥3,000	¥3,500	no changes
	Cam pro le design fee		34108140	¥28,000	¥35,000	

OTHERS					
Service	Application	P/N	JPY	NEW JPY	NOTE
Transmission overhau	NISSAN 56A,60A	34103010	¥90,000	¥100,000	no changes
	NISSAN 71B,71C	34103020	¥90,000	¥100,000	
	NISSAN FS5R30A	34103030	¥120,000	¥140,000	
	HOLINGER	34103040	¥100,000	¥120,000	
Transfer overhaul	BNR32/33/34	34104010	¥68,000	¥110,000	no changes
Exchange di gear	H type	34105010	¥55,000	¥75,000	
	R type	34105020	¥45,000	¥65,000	
LSD insert		34108150	¥29,000	¥32,000	
LSD overhau		34108000	¥29,000	¥32,000	
Tensioner Height Adjustment		34109010	¥3,500	¥3,500	no changes